

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3670	DATE	October 23 rd , 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to the insufficient weld connection in one batch of forward/back adjustment units of the front seat structures, the connection might fail in case of an accident, and noise or rattling may occur. In worst case, the restraint function might be impaired.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-22EH30	「BMW 740i」	2022	7
3CA-22EJ30	「BMW 740d xDrive」	2022	10
ZAA-52EJ89	「BMW i7 xDrive60」	2022	6
		TOTAL	23