

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3709	DATE	Oct. 20. 2023
MANUFACTURER	Ford Motor Company		
DESCRIPTION OF DEFECT	<p>SAFETY RECALL: Navigator - Climate Control Blower Motor Replacement - Certain vehicles built during this time frame may pose a risk of interior fire while the vehicle is on. Ford Motor Company is working with its suppliers to provide remedy parts for this concern.</p> <p>Dealers are to replace the climate control front blower motor. This service must be performed on all affected vehicles at no charge to the vehicle owner.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	Lincoln Navigator	2015 - 2016	44 units
TOTAL			44 units