

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3707	DATE	October 18, 2023
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer :Stellantis Japan Ltd. )		
DESCRIPTION OF DEFECT	Exhaust pipe clamp was not properly tightened, and the exhaust pipes may be disconnected. Then, exhaust gas may leak with noise and engine check light may turn on. In the worst case, there is a risk of thermal incident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-P51YH01	「308」	2022	2
3DA-P52YH01	「308」	2022	32
		TOTAL	34