

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3699	DATE	October 5, 2023
MANUFACTURE	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the fuel supply module located in the fuel tank, the component design of the fuel supply module flange part is inappropriate. When high ambient temperature, coupled with poor fuel quality, may cause excess current to flow, the upper electrical connector may overheat and melt the flange material. Therefore, it could result in a small fuel leak towards the top of the fuel tank. In the worst case, a fuel leak can increase the risk of a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-BADDB	Bentayga W12	2017 – 2020	373
7BA-BADDB	Bentayga W12 Speed	2020 – 2023	101
		TOTAL	474