

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	外-3701	DATE	October 5. 2023
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	Due to inappropriate parts in the shift lever of agricultural tractors, the wrong drive command may be recognized when the lever is operated strongly to the end in the low speed range (0-2km/h). Therefore, in the worst case, the tractor may move in a direction different from the intended direction.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「JD-6215R」	2021	1	
		TOTAL	1	