

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai – 3710	DATE	30 November, 2023
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	For the high voltage battery, sealing is incomplete due to insufficient application of sealant in the production process. Therefore, it is possible that the battery becomes abnormal condition by heat because arcing occurs while insulated resistance would be reduced if moisture comes into the battery then fire may occur in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-J1MB	Taycan 4S	2021-2023	1
ZAA-J1MC	Taycan Turbo		1
ZAA-J1NA1	Taycan		45
ZAA-J1NA1C	Taycan		37
ZAA-J1NA2	Taycan 4		45
ZAA-J1NB	Taycan 4S		86
ZAA-J1NC	Taycan Turbo		43
ZAA-J1ND	Taycan Turbo S		28
ZAA-J1NE	Taycan GTS		67
			Total