

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	外-3723	DATE	2023/12/1
MANUFACTURER	FENDT (Japanese Importer :MSK Farm Machinery Corporation CEO Takahata Toshinobu)		
DESCRIPTION OF DEFECT	<p>The strength of the stud bolts of the fixing fittings for the steering control units on the steering columns is insufficient. Therefore, if you continue to use the vehicle as it is, the stud bolt may break, resulting in the steering control unit will drop, and the fitting part of the steering column (shaft) will come off, making steering difficult. We will inspect the stud bolts and replace the fitting part with correct one.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
不明	F933VARIO G7	2022	1
不明	F936VARIO G6	2021	2
		TOTAL	3

(日本工業規格A列4番)