

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3752	Date	December 22, 2023
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to a potentially wrong assembly of the heatshield of the brake booster, it's possible that the brake fluid reservoir can be damaged. The assembly of the heatshield may not be done properly. Due to the possible damage of the brake fluid reservoir by high temperatures in engine compartment at high engine load, it's possible that brake fluid can leak. If the brake fluid will get in touch with hot surfaces, it's possible that the brake fluid can ignite.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-CDDNP	Golf GTI 2.0/180kW	2022-2023	1,259
3BA-CDDNFF	Golf R 2.0/235kW	2022-2023	34
3BA-CDDNFV	Golf R Variant 2.0/235kW	2023	26
3DA-CDDTT	Golf TDI/110kW	2023	78
3DA-CDDTS	Golf TDI/110kW	2021-2022	802
3DA-CDDTSV	Golf Variant TDI/110kW	2021-2022	2
3DA-3CDFH	Passat TDI/140kW	2021-2022	409
	Passat Variant TDI/140kW	2021-2024	1,026
	Passat Alltrack TDI/140kW	2021-2024	568
3BA-3HDNUF	Arteon 2.0/200kW	2021-2023	2,308
		Total	6,512