

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3742	DATE	Dec. 8th, 2023
MANUFACTURE	McLaren Automotive (Japanese Importer : McLaren Automotive Asia Pte Ltd.)		
DESCRIPTION OF DEFECT	A defective pipe within the low pressure fuel pipe assembly can potentially become disconnected, particularly during the engine start process. In the event the pipe becomes disconnected, there could be a fuel leak. Because the connections are situated close to engine components which have a high operating temperature, such a leak could increase the risk of a thermal event.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7LA-MA6	McLaren Artura	2023	39
		TOTAL	39