

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3731	DATE	December 6 <sup>th</sup> , 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>The defect involves the integrated electronic transmission control unit "iTCU". Due to a manufacturing fault, the weld seam of the two halves of the control unit's housing may be insufficient.</p> <p>In case of an improper welding seam, an ingress of the automatic transmission oil may occur over lifetime and short circuits are potentially possible . In worst case, this could lead to the transmission jamming</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-5V20	「BMW 320d xDrive」	2023	3
3DA-UZ20	「BMW X3 xDrive20d」	2023	20
3DA-32AX20	「BMW 420d xDrive」	2023	14
3BA-HF20	「BMW Z4 sDrive 20i」	2023	3
3DA-JF20	「BMW 523d xDrive」	2023	15
3DA-JP20	「BMW 523d xDrive」	2023	1
3BA-JT20T	「BMW 530i」	2023	2
7BA-82CH44	「BMW M5」	2023	1
3BA-AE30	「BMW 840i」	2023	1
		TOTAL	60