

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3684	DATE	December 4th, 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to a manufacturing defect that the 48 V lead from the starter generator to the body was not bolted correctly, functional limitations may occur on the engine start-stop system, even while driving. In certain situations, this can cause the vehicle to coast without warning. In addition, it cannot be completely ruled out that increased contact resistance may result in localized scorching marks in the engine compartment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-UZ7230	「BMW X3 M40d」	2022	2
		TOTAL	2