## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	外3763	DATE	30th. Jan. 2024	
MANUFACTURE	DFSK			
	(Japanese Importer : fo	olofly inc.	)	
DESCRIPTION OF DEFECT	On cars equipped with ESC, there is an error in the connection between the ESC actuator and brake pipe.			
	In the worst case, the vehicle's behavior may become unstable when ESC is activated, and the brake system may not meet standards.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
N/A	folofly F1VS	2023	13
		TOTAL	13