

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

|                       |  |      |                 |
|-----------------------|--|------|-----------------|
| CAMPAIGN No.          | GAI-3789   | DATE | 29th March 2024 |
| MANUFACTURE           | Triumph Motorcycles Limited<br>(Japanese Importer : Triumph Motorcycles Japan K.K. )   |      |                 |
| DESCRIPTION OF DEFECT | <p>The threads on certain front fork caps may strip, leading to a detachment of the cap from the fork outer tube. A detached defective front fork cap from the outer leg will compromise the operation of the front suspension which potentially increases the risk of a crash.</p> <p>A defective fork cap that has not detached from the outer leg, will not compromise the operation of the front suspension, and will continue to operate correctly but will also require replacement.</p> |      |                 |

|            |             |       |     |
|------------|-------------|-------|-----|
| 8BL-LUJ660 | Trident     | 2023  | 84  |
|            | Tiger Sport | 2023  | 29  |
|            |             | TOTAL | 113 |