

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-3773	DATE	March 15, 2024
MANUFACTURE	Indian Motorcycle Polaris Japan Inc		
DESCRIPTION OF DEFECT	<p>① The fuel evaporative emission countermeasure function does not work because a program with a different specification was written in the computer (ECU) that controls the engine. Therefore, the fuel evaporative gas is not drawn into the intake system, and when the fuel evaporative gas adsorption capacity of the canister is exceeded, it is released into the atmosphere, and the fuel evaporative gas emission amount does not meet safety standards. Also OBD doesn't detect this malfunction.</p> <p>② Due to inappropriate program settings in the computer (ECU) that controls the engine, the correct speed will not be displayed on the speedometer until the engine speed exceeds a certain number. Therefore, the driver may not be able to recognize the speed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-D DBABH DLABH DMABH	Chief Bobber Dark Horse Chief Dark Horse Sport Chief Super Chief Limited	2021~2023	① 117 ② 68
8BL-L	Indian Challenger Dark Horse Indian Challenger Elite Indian Challenger Limited Indian Pursuit Dark Horse with Premium Package Indian Pursuit Limited with Premium Package	2021~2022	① 16
		TOTAL	201