

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	外-3774	DATE	March 15th 2024
MANUFACTURE	Bombardier Recreational Products Inc. Japanese Importer : BRP Japan		
DESCRIPTION OF DEFECT	Due to improper raw material is used, the impeller in the fuel pump may swell. This will cause the fuel supply from fuel tank to the engine to stop and cause the engine to stall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2FF 2FG 2GG,2HH 2JG	Can-Am RYKER600 Can-Am RYKER900 Can-Am RYKER RALLY Can-Am RYKER SPORT	6 March 2021 to 28 Feb 2022	73
		TOTAL	73