

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3815	Date	May 30, 2024
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	The bolting process of the front seats between backrest and seat pan may be incorrectly carried out due to inappropriate manufacturing control. The restraint effect of the seat may be insufficient in the event of an accident. In the worst case, there is therefore an increased risk for occupants.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-E2EBJ	ID.4	2023	107
		Total	107