

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-3797	Date	May. 14, 2024
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	In the event of a rear turn signal indicator electrical failure, the frequency tell-tale illumination and audible 'tick tock' are unchanged. The frequency tell-tale and audible 'tick tock' will flash at a normal rate. Absence of warning of electrical failure of the rear turn signal indicator, may result in the driver being unaware of a failure.  Update the Gateway module program.		

Type	Commercial name	Model year recalled	Number of vehicles
ZAA-DH1AA	I-PACE	2022-2024	50
ZAA-DH1CA		2022	10
		2022-2024	60

(JIS A4 size)