

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3808	DATE	8 th May 2024
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.)		
DESCRIPTION OF DEFECT	In conditions of high ambient temperature and slow-moving traffic, the radiator fan may surpass its maximum operating temperature, resulting in fan motor failure. Ignoring the warning light on the instrument panel and continuing to ride at low speeds may potentially cause coolant displacement, thereby increasing the risk of a crash.		

2BL-PSJ1200	Speed Triple RS	2021-2022	297
8BL-PSJ1200	Speed Triple RS	2021-2023	74
	Speed Triple RR	2021-2023	296
		TOTAL	667