

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3787	DATE	26 th June, 2024
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate conditions in the production process, there is a possibility that signal interference in the electronics of the brake system may occur. In this case, the brake warning lights lighting up and Check Control message will be displayed. Also, an unexpected loss of hydraulic brake assist may occur and may result in an extended braking distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-22BY20	「BMW 218d Active Tourer」	2022 - 2023	1,060
3BA-62BX15	「BMW 218i Active Tourer」	2022 - 2023	742
3AA-12FJ20	「BMW 523i」	2023	2
3CA-22EJ30	「BMW 740d xDrive」	2022 - 2023	315
3AA-22EH30	「BMW 740i」	2022 - 2023	439
ZAA-42FK89	「BMW i5 M60 xDrive」	2023	2
ZAA-42EJ49	「BMW i7 eDrive50」	2023	6
ZAA-82EH93	「BMW i7 M70 xDrive」	2023	2
ZAA-52EJ89	「BMW i7 xDrive60」	2022 - 2023	259
ZAA-62EF67	「BMW iX1 xDrive30」	2022 - 2023	349
3CA-42EG20	「BMW X1 xDrive20d」	2023	1,173
3BA-52EE20	「BMW X1 xDrive20i」	2022 - 2023	1,501
3AA-32EU44A	「BMW X5 M60i xDrive」	2023	32
3CA-12EV30A	「BMW X5 xDrive 35d」	2023	1
3LA-42EU30	「BMW X5 xDrive 50e」	2023	64
3AA-12ET44	「BMW X5M Competition」	2023	10
3AA-42EX44	「BMW X6 M60i xDrive」	2023	34
3CA-12EY30S	「BMW X6 xDrive35d」	2023	2
3AA-12ET44	「BMW X6M Competition」	2023	11
3AA-32EM44	「BMW X7 M60i xDrive」	2022 - 2023	140
3CA-22EN30	「BMW X7 xDrive40d」	2022 - 2023	566
3LA-22CS44	「BMW XM」	2022 - 2023	155
		TOTAL	6,865