

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-3814	DATE	June 24 th , 2024
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	It is possible that the head restraint guide sleeves in the area of the backrest frame (centre section) on the rear seat of the vehicles concerned may not have been welded correctly. In an accident situation, it cannot be ruled out that the restraint function of the affected head restraint is no longer available.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-42EG20	「BMW X1 xDrive20d」	2023	1
		TOTAL	1