

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3821	DATE	June 21, 2024
MANUFACTURE	FCA US LLC (Japanese Importer : Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	The power liftgate control module may experience a corrosion induced high resistance short circuit in the power liftgate module electrical connector(s). The power liftgate module electrical connector(s) could allow water intrusion and cause the module to become inoperative and/or cause a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-KL24	Jeep Cherokee	2014	181
ABA-KL32	Jeep Cherokee	2014	329
ABA-KL32L	Jeep Cherokee	2014	238
ABA-KL24	Cherokee	2014	145
ABA-KL24P	Cherokee	2015	153
ABA-KL32	Cherokee	2014	148
ABA-KL32L	Cherokee	2014-2015	67
		TOTAL	1,261