

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3824	DATE	June 21, 2024
MANUFACTURE	FCA US LLC (Japanese Importer : Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	The Upper Control Arm (UCA) pinch bolt may have been damaged during vehicle assembly. A damaged pinch bolt may break and result in the loss of clamp load between the UCA ball joint and the knuckle. A loss of clamp load may result in the UCA separating from the knuckle and the wheel falling outboard, which can cause a vehicle crash without prior warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-WL20	Grand Cherokee	2023	136
3LA-WL20A	Grand Cherokee	2023	237
7BA-WL20	Grand Cherokee	2022-2023	822
7BA-WL36L	Grand Cherokee L	2021-2023	1,337
7BA-WL36LA	Grand Cherokee L	2021-2023	667
7LA-WL20A	Grand Cherokee	2022	1
		TOTAL	3,200