

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-3711	DATE	June. 13 th , 2024
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to a manufacturing defect, the drive shaft may come loose from the ball hub of the eDrive motor under certain circumstances. In rare cases, this may lead to a loss of drive power when driving off and cause the vehicle to coast.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-62EF67	BMW iX1 xDrive30	2023	83
		TOTAL	83