

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	外-3825	DATE	June 10. 2024
MANUFACTURER	JOHN DEERE (Japanese importer:YANMAR AGRIBUSINESS CO.,LTD.)		
DESCRIPTION OF DEFECT	In some agricultural tractor front suspensions, the ball joints are not properly attached to the knuckle housing due to improper assembly. If the tractor is continued to be driven in this condition, the ball joints may wear out prematurely or the knuckle housing may be damaged, and in the worst case, the parts around housing may break, making it impossible to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「JD-8R370」	2022	1	
		TOTAL	1	