

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3826	DATE	10. 06. 2024
MANUFACTURER	Royal Enfield (A unit of Eicher Motors Ltd.) (Japanese Importer : PCI.co.Ltd)		
DESCRIPTION OF DEFECT	Due to insufficient confirmation of the contents of the noise label and VIN label, the noise value and measured rotation speed of nearby exhaust noise are incorrect. Therefore, it does not comply with Agreement Regulation No. 41. In addition, there are cases in which incorrect noise values and measured rotational speeds are written in the notes section of automobile inspection certificates.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ME3ESP15	SUPER METEOR 650	2023	68 units
TOTAL			68 units