

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic／Import Vehicles

CAMPAIGN No.	Gai-3838	DATE	July 10, 2024	
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)			
DESCRIPTION OF DEFECT	With regards to the two-axle 5th coupler for heavy duty tractors, due to the inappropriate lock guard shape which was amended for better production workability, if the driver connects tractor and trailer without ensuring the appropriate height, the lock guard could not avoid inappropriate coupling, but the 5th coupler coupling confirmation lamp activates in the driver seat center panel. Thus, if the driver keeps vehicle operation without visually confirming the 5th coupler connection, the tractor and the trailer might be detached while driving.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2DG-5S4TBA1	FH	2022-2023	69	
2DG-5S4TBL1		2022	1	
2DG-5S4TCA1		2023	9	
		TOTAL	79	