

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3830	DATE	July 8, 2024
MANUFACTURE	Aston Martin Lagonda Limited (Japanese Importer : Aston Martin Japan Limited)		
DESCRIPTION OF DEFECT	In three nuts securing the power supply wires of the 12 V battery fuse box, insufficient tightening torque during the manufacturing process may cause the nuts to loosen during use. As a result, the vehicle's power supply could be compromised and, in the worst case, the engine could stop while the vehicle is running and not be restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-AM801	DBX	2020-2023	482
	DBX707	2022-2023	236
		TOTAL	718