

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3831	DATE	July 8, 2024
MANUFACTURE	Aston Martin Lagonda Limited (Japanese Importer : Aston Martin Japan Limited)		
DESCRIPTION OF DEFECT	In some front propeller shafts and front differentials, the bolts securing them are not tightened to the specified torque due to inadequate work control during manufacture. As a result, said bolts loosen, causing noise and vibration when driving and loss of drive to the front wheels. In the worst case, if the crankshaft sensor is damaged by the dislodged propeller shaft, the engine may stop and cannot be restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-AM801	DBX	2020	1
		TOTAL	1