

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-3833	Date	July. 2, 2024
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	The incorrect specification plastic housing will, over time and with vehicle use, crack allowing oil to leak out onto the engine and into the engine bay. An oil leak under pressure in this area could result in oil coming into contact with hot components on the engine which may result in a fire. Vehicles will have the oil filter housing, complete with filter and associated O-rings, replaced.		

Type	Commercial name	Model year recalled	Number of vehicles
3AA-L123UA	Range Rover Sport	2024	10
3CA-L123WA			10
3CA-LE62WAB	DEFENDER 90		5
3CA-LE72WAB	DEFENDER 110/ DEFENDER 130		90
3CA-LE72WCB	DEFENDER 110		10
3CA-LK93WA	Range Rover		14
		2024	139

(JIS A4 size)