

第 3 号様式（英文リコール概要書）（第 2 関係）

TIRE SAFETY RECALL CAMPAIGN IN JAPAN				
Domestic Tires				
CAMPAIGN No.	装 17	DATE	July 3rd, 2024	
MANUFACTURER	The Yokohama Rubber Co.,Ltd.			
DESCRIPTION OF DEFECT	Tire（Possible air leakage from beads） Due to improper operation in a certain manufacturing process, some of the subject tires may have been manufactured with nylon cords visible at the bead area, inside of the tire. Tires containing visible nylon cords may have leak air slowly, and if undetected or ignored, the continual loss of air may make driving impossible. The tires of the subject serial will be inspected, and the corresponding tires will be replaced with good ones.			
COMMERCIAL NAME	TYPE	CLASSIFICATION	MODEL YEAR RECALLED	NUMBER OF ITEMS
Y-103	10-16.5 4PR TUBELESS	For Construction Ⅲ	2PGG YYY 2822 ～ 1324 Jul. 1st, 2022 ～Mar. 30th, 2024	21
Y-103	10-16.5 6PR TUBELESS	For Construction Ⅲ	2PGG YYY 2822 ～ 1324 Jul. 1st, 2022 ～Mar. 30th, 2024	41
			Total	62