

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-3862	Date	2024/8/30
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	The Final Drive Bolts needs to be replaced on certain Wheel Loaders 918M and 920. The existing Final Drive Bolts can fail and cause noise from the final drive, oil leak, wheel locking and/or wheel separating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-H26	「918M」	2018 to 2020	164
YDR-SL4	「920」	2020 to 2022	65
		TOTAL	229