

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3854	DATE	2024/8/22
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan G.K.)		
DESCRIPTION OF DEFECT	On certain C-Class (206 platform) vehicles the bolting of an electrical wire on the pre-fuse box in the passenger-side footwell might have been tightened with an insufficient torque. As a result, a sudden loss of propulsion without prewarning cannot be ruled out. In addition, the electrical contact resistance at this connection point could increase. Consequently, due to the high electrical currents that can flow through this connection, the temperature in this area could rise, which could increase the risk of fire. Furthermore, legal requirements might not be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-206041C	C180	2022	14
		2023	2
5AA-206042C	C200	2022	63
5AA-206043C	C200 4MATIC	2022	14
3CA-206004C	C220d	2022	46
		2023	1
4AA-206087C	Mercedes-AMG C43 4MATIC	2022	2
		TOTAL	142