VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

DAT	E	August. 19 th , 2024	
BMW (Japanese Importer: BMW Group Japan Corp.)			
Due to the change in the routing of the cylinder head ventilation line, there is			
a possibility that the bleed line may interfere with the engine wire harness and			
cause chafing. The chafe mark may cause the cylinder head ventilation line to leak over the service life of the vehicle which affects the safety regulation.			
li	apanese Importer: Be e change in the routing lity that the bleed line r afing. The chafe mark	apanese Importer: BMW Group Japan C e change in the routing of the cylinder head lity that the bleed line may interfere with the afing. The chafe mark may cause the cylind	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-5V20	BMW 320d xDrive	2021 - 2023	1,690
3DA-6L20	BMW 320d xDrive	2021 - 2023	1,563
3DA-32AX20	BMW 420d xDrive	2022 - 2023	1,086
		TOTAL	4,339