

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3847	DATE	1 August, 2024
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	For braking system, the length of front brake hoses is insufficient due to improper design. Therefore, significant tension caused by steering angle may be applied and cracks may occur on the front axle brake hoses while vehicle in use. In the worst case, brake fluid may leak and the warning message appears on the instrument cluster, then the braking performance could be noticeably restricted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-J1MB	Taycan 4S	2021 - 2025	330
ZAA-J1NB			389
ZAA-J1MC	Taycan Turbo		104
ZAA-J1NC			135
ZAA-J1SO			1
ZAA-J1MD	Taycan Turbo S		114
ZAA-J1ND			94
ZAA-J1NA1	Taycan		367
ZAA-J1NA1C			491
ZAA-J1NA2	Taycan 4		275
ZAA-J1NE	Taycan GTS		304
		Total	2,604