

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-3883	Date	Sep. 24, 2024
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	The incorrect specification plastic housing will, over time and with vehicle use, crack allowing oil to leak out onto the engine and into the engine bay. An oil leak under pressure in this area could result in oil coming into contact with hot components on the engine which may result in a fire. Vehicles will have the oil filter housing, complete with filter and associated O-rings, replaced.		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-L123WA	Range Rover Sport	2024	6
3CA-LE62WAB	DEFENDER 90		1
3CA-LE72WAB	DEFENDER 110		1
3CA-LK93WA	Range Rover		2
		2024	10

(JIS A4 size)