

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3868	DATE	19, Sep, 2024
MANUFACTURER	Automobili Lamborghini SpA (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	The affected vehicles may have some rivet studs that fix the hood latch strikers with insufficient deformation. If under-deformed rivet studs are used on the same latch striker, small gaps between the hood and front bumper may start to develop at high speeds, allowing air to enter. These gaps can potentially increase at high speeds, and over time, the stress can cause the latch system to fail, separating the hood latch striker from the hood.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA- ZLDHU	URUS	2023-2024	146
7BA- ZLDWN		2023-2024	228