

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	3859	DATE	xxxx xx, 2024
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	In the in-tank unit of the fuel pump, the impeller may deform when the fuel temperature rises due to the improper selection of the impeller material, or foreign matter may get into the inside of the pump due to an improper manufacturing process. This may cause the fuel pump to malfunction, and in the worst case, the engine may stop while driving and be unable to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-BBM5P	MEGANE R.S.	2018 - 2020	922
7BA-BBM5P		2019 – 2020	502
7BA-BBM5P1		2020 – 2022	1,186
		TOTAL	2,610