

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic(~~Import~~) Vehicles

CAMPAIGN No.	gai—3869	DATE	September 6, 2024
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	The aluminum bracket (support stay) that fixes to the master cylinder of the front brake fluid reservoir tank is not strong enough. As a result, the support stay may bend due to vibrations while riding, and in the worst case, it may break.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-DC00	Superleggera V4	2020 – 2021	28
2BL-1D00	Panigale V4 Panigale V4 S Panigale V4 SP	2021	216
2BL-3D00	Panigale V4 S	2022	63
8BL-3D00	Panigale V4 Panigale V4 S Panigale V4 SP2 Panigale V4 2022 WCR	2023 – 2024 2023 – 2024 2022 – 2024 2024	198
8BL-3D06	Panigale V4 R	2023 – 2024	139
		TOTAL	644