## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Import Vehicles

CAMPAIGN No.	Gai-3865	DATE	30 <sup>th</sup> Oct, 2024		
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)				
DESCRIPTION OF DEFECT	could become leaky over leakage in combination temperatures normally smoldering particles. The	On affected diesel vehicles, EGR (Exhaust-Gas-Recirculation) cooler could become leaky over time due to insufficient durability. The glycolleakage in combination with typical soot deposits and the high temperatures normally present in the EGR module, might result in smoldering particles. This could lead in very rare cases to the melting of the intake manifold and in extremely rare cases result in a possible			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-WY20	「BMW X3 xDrive20d」	2014 – 2015	48
LDA-3D20	「BMW 320d」	2014 – 2015	17