

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	GAI 3891	DATE	18.Oct.2024
MANUFACTURE	BMW (Japanese Importer)		
DESCRIPTION OF DEFECT	BMW Motorrad has established that due to insufficient sealing of the control unit, moisture can penetrate the reverser control unit (optional equipment). This moisture can lead to corrosion of electrical contacts inside the control unit over time (usually vehicle age > 24 months) and under certain climatic conditions (tropical/warm-humid all year round). This corrosion can result in operating failure of the control unit (failure of the reverser comfort function).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-R187A	BMW R18 Pure	2020 – 2021	411
2BL-R187A	BMW R18 Classic	2020 – 2021	175
8BL-R187A	BMW R18 Pure	2021 – 2024	316
8BL-R187A	BMW R18 Classic	2022 – 2024	227
8BL-R187A	BMW R18 B	2021 – 2024	237
8BL-R187A	BMW R18 Roctane	2023 – 2024	161
8BL-R187A	BMW R18 Transcontinental	2021 – 2024	210
		TOTAL	1,737