

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3872	DATE	October 10, 2024
MANUFACTURE	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	For the engine control unit, due to sub-optimal configuration of the OBD (On Board Diagnostics) system, the crankshaft position component may not be monitored correctly under at cold engine conditions and at engine speeds higher than 2.500 rpm. Consequently, it will lead to a limited misfire detection capability and an emission control system warning light (MIL) will not illuminate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-BADCU	Bentayga V8	2018 – 2020	241
		TOTAL	241