

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	GAI-3875	DATE	2024/10/2
MANUFACTURER	Massey Ferguson (Japanese Importer :MSK Farm Machinery Corporation CEO Takahata Toshinobu)		
DESCRIPTION OF DEFECT	There is a possibility that the plug loosens due to an excessive manufacturing error of the plug hole on the transmission valve block. Therefore, if you continue driving, there is a possibility that the plug comes off, and the oil leaks from the driving hydraulic circuit, and driving becomes impossible. We will inspect the serial number of the affected valve block and replace valve block with correct one in case of affected serial number.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-SU66A7S	MF7S210EXDV	2023	3
YDS-SU66A7S	MF7S180EXDV	2023	2
—	MF6S165EXDV	2023	4
		TOTAL	9