VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3877	DATE	November 18 th , 2024		
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)				
DESCRIPTION OF DEFECT	Due to manufacturing error, EGR (Exhaust-Gas-Recirculation) cooler could become leaky. The glycol-leakage in combination with typical soot deposits and the high temperatures normally present in the EGR module, might result in smoldering particles. This could lead in very rare cases to the melting of the intake manifold and in extremely rare cases result in a possible fire.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-5V20	「BMW 320d xDrive」	2019 - 2022	5,711
3DA-6L20	「BMW 320d xDrive Tr.」	2019 - 2021	3,805
3DA-JF20	「BMW 523d」	2019	1
3DA-JF20	「BMW 523d xDrive」	2019 - 2020	797
3DA-JP20	「BMW 523d xDrive Touring」	2019 - 2020	279
3DA-JX20	「BMW 623d Gran Turismo」	2019	32
3DA-UZ20	「BMW X3 xDrive20d」	2019 - 2021	2,888
3DA-VJ20	「BMW X4 xDrive20d」	2019 - 2021	1,001
		TOTAL	14,514