

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3900	Date	November 14, 2024
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In a driver airbag inflator, the propellant can deteriorate because of high humidity environment and temperature fluctuations. As a result, container of the inflator may rupture when airbag deploy.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-16CBZ	VW The Beetle 1.2/77kW	MY2017-MY2019	7,046
ABA-16CPL	VW The Beetle 2.0T	MY2017-MY2019	695
ABA-16CZD	The Beetle 1.4/110kW	MY2017-MY2019	1,267
ABA-16CZDW	The Beetle DUNE 1.4/110kW	MY2017	294
		Total	9,302