

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-3897	DATE	November 11, 2024
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In tailgate cover composed of an outer panel and an internal bracket, the outer panel may partially get detached due to insufficient adhesion during manufacturing. Therefore, abnormal noise could generated due to driving vibration, If you continue driving in this condition, the outer panel may fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-22CS44	「BMW XM LABEL」	2023	1
		TOTAL	1