

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-3896	DATE	Nov. 8th, 2024
MANUFACTURER	ALPINA Bruckard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	Due to a manufacturing defect, the coupling rod of the exhaust gas recirculation module may break. Therefore, valve flaps cannot be switched, and the motor control activates a fault mode where the EGR is deactivated. The MIL is activated, and it may happen that the exhaust gas limits are exceeded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-UU40	XD3	2023	19
7CA-3U40	D3S		21
	D3S Touring		22
7CA-4U40	D4S		25
7CA-5U40	D5S		20
		TOTAL	97