

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3917	DATE	19, Dec, 2024
MANUFACTURER	Automobili Lamborghini SpA (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the affected vehicles the connecting rod between the passenger wiper arm and the wiper motor may bend causing its separation from the wiper motor. If the connecting rod separates, the wiper becomes inoperative. Inoperative windshield wipers can reduce visibility in certain conditions, increasing the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7LA-ZMREV	REVUELTO	2024	90