

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-3913	Date	December 12, 2024
Manufacturer	Caterpillar Inc. (Caterpillar Japan LLC)		
Description of Defect	The bolts for fixing the seat mount bracket on the CAB has a possibility to be loose due to inadequate instruction for mfg after a seat riser design change. Therefore, if the usage under this defect were kept as it was, this seat will be unstable condition and maybe separated from CAB in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-M5T	「950GC」	2023, 2024	11
YDS-SG7	「966GC」	2023, 2024	3
		TOTAL	14