

VEHICLE SAFETY/~~POLLUTION~~ RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-3904	DATE	December/11/2024
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Volvo Cars have identified that cars might have been produced without grease in the rear CV joint on the propeller shaft, This may cause vibration and noise.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[XC40]	2025	32
TOTAL			32