VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



| CAMPAIGN No. | 外-3932 | DATE | January 28. 2025 | | | |
|-----------------------|--|------|------------------|--|--|--|
| MANUFACTURER | JOHN DEERE (Japanese importer:YANMAR AGRIBUSINESS CO.,LTD.) | | | | | |
| DESCRIPTION OF DEFECT | are stamped as small special nounting bolts of the cylinders ine at the wheel fulcrum is continues to be used in this fall off, interfering with the | | | | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | | NUMBER OF VEHICLE | |
|------|--------------------|------------------------|-------|----------------------|--|
| _ | ID 1755 | 2021 | | 8 | |
| | JD-1755 | 2022 | | 1 | |
| | | | TOTAL | 9 | |